When does one use which control unit?



MiniMax

Odd input signals

Extra cards

Spec. settings

External operation conditions



MicroMax

Standard control unit



VariMax CE

Gearbox-free

Extreme low/high speed for rotor

A1-A2, sep. adj. of speed

Also available in Modbus version



VariMax NG

Gearbox-free

Extreme low/high speed for rotor

A1-A2, sep. adj. of speed

Internal rotation monitor

Integrated Modbus

Compact build dimensions

Control system of the future



MicroStart

Small units

Affordable