



Common to all control units

Functions

- Rotation monitor
- Cleaning function
- Manual run
- Push-button reset

Settings

- Adjustable high-speed
- Fixed adjustable low-speed (MiniMax adjustable)
- A1-A2 (some)
- Starts automatically after voltage drop-out

Indications / alarm

- Operational indications
- Alarm indications
- Alarm retention
- Buzzer alarm outlet
- Thermal contact in the motor (not VariMax NG)

Approval

- CE-approved
- EMC-approved